

Glass Vice® tubular care & maintenance

To maintain the appearance and protective properties of your powder coated surfaces, you need to routinely clean the surface to remove dirt and grime.

All you need is a gentle clean with a soft brush and mild detergent, followed by a fresh water rinse.

In normal environments cleaning should occur every 12 months, in coastal areas or environments, cleaning should occur every 3 months. In beach front, marine environments, cleaning should occur monthly.
